

| Line No.     | Line / ID                                   | Start Date | From Station         | End Date   | Short Description / Purpose of Request   | System Restrictions  | Project Owner                       |
|--------------|---|------------|----------------------|------------|--|--|-------------------------------------|
| L-7022       | L7022 Outage                                | 4/17/2018  | 101S-Woodbine        | 4/29/2018  | L7022 outage for structure and insulator replacements.                                 |  | Transmission Group (Ragged Lake)    |
| L-6552       | 4C-620                                      | 4/23/2018  | 4C-Antigonish (Loch. | 4/25/2018  | Isolation of 4C-620 for the annual C-maintenance.                                      | Reducing SPS Arming Levels Limiting Onslow Import based on the sum of the total Generation       | System Maintenance                  |
| L-5027       | L5027 / 25W-504 Replacement                 | 4/23/2018  | 9W - Tusket Hydro    | 4/27/2018  | Switching to Isolate 25W-504 for replacement (part of the L5027 transmission upgrades) |  | System Maintenance                  |
| L-7003       | L7003 Outage                                | 4/26/2018  | 67N-Onslow           | 5/18/2018  | L7003 Outage for structure and insulator replacements.                                 | CBX 620 /720, Onslow Import 755 /795, lower SPS arming levels                                    | Transmission Group (Ragged Lake)    |
| L-6533       | 88S-B71, 88S-710, 88S-T71, 88S-711          | 5/1/2018   | 2S-Victoria Junction | 6/10/2018  | replacement of the Westinghouse GIS equipment at 88S Lingan                            | 88S-T71 out of service Limit flow through 88ST72 to 170MW Operate local units in synchronous cor | Transmission Engineering (Lakeside) |
| L-6012       | 17V-P6011                                   | 5/7/2018   | 17V-St. Croix        | 5/8/2018   | • B71 Outage, includes breaker 710, T71, and L-6533                                    |  | System Maintenance                  |
| L-6511       | 50N-614                                     | 5/7/2018   | 50N-Trenton          | 5/9/2018   | C Inspection PT 17V-P6011  | Onslow Import: 650MW to Normal depending on Generation in the area, SPS arming levels reduced    | System Maintenance                  |
| L-6013       | 43V-P6013                                   | 5/14/2018  | 43V-Canaan Rd.       | 5/15/2018  | C Inspection 50N-614   |  | System Maintenance                  |
| L-6021       | 9W-516                                      | 5/14/2018  | 30W-Souriquois       | 5/16/2018  | C Inspection 43V-P6013   |  | System Maintenance                  |
| L-7005       | L-7005                                      | 5/14/2018  | 67N-Onslow           | 5/19/2018  | 7005 - PART OF THE SWAP AT THE CAUSEWAY  | Cape Breton Export 620 /720, Onslow Import 755 /795, SPS arming levels reduced.                  | Mainland at H Outside Group         |
| L-8004       | L-8004                                      | 5/20/2018  | 79N-Hopewell         | 5/25/2018  | Parallel Conductors on existing Straight Crossing Tower                                | Hastings From 600MW /625*, L7011+L7012 500 /600, Mainland at Hastings 590 /680, Generation n     | Maritime Link                       |
| L-7014       | 101S-703A & 702B                            | 5/21/2018  | 88S - Lingan         | 5/21/2018  | Woodbine Disconnect Switches 703A, 702B  | Generation restrictions apply, SPS levels adjusted,  | Maritime Link                       |
| L-6004       | 43V-P6004                                   | 5/21/2018  | 90H-Sackville        | 5/22/2018  | C Inspection 43V-P6004   |  | System Maintenance                  |
| L-7014       | 88S-L7014                                   | 5/21/2018  | 88S - Lingan         | 5/23/2018  | 88S-L7014 NPCC Testing   | Generation restrictions apply, SPS levels adjusted,  | System Maintenance                  |
| L-7011       | L-7011                                      | 5/23/2018  | 3C-Port Hastings     | 5/24/2018  | Woodbine breakers 101S-704B, 705A, 751   | East End X at East Bay - 675 MW, CBX 700 MW, Generation restrictions apply, Lower SPS arming lin | Maritime Link                       |
| L-7021       | L-7021                                      | 5/25/2018  | 101S-Woodbine        | 5/26/2018  | Woodbine Switches 101S-712A, 711B, 752   |  | Maritime Link                       |
| L-8004       | 101S-812B & 813A                            | 5/28/2018  | 79N-Hopewell         | 5/28/2018  | Woodbine Disconnect Switches 812B, 813A  | Hastings From 600MW /625*, L7011+L7012 500 /600, Mainland at Hastings 590 /680, Generation n     | Maritime Link                       |
| L-6013       | 43V-613                                     | 5/28/2018  | 43V-Canaan Rd.       | 5/30/2018  | C Inspection 43V-613   |  | System Maintenance                  |
| 101S-T82     | 101S-B82                                    | 5/29/2018  | 101S-Woodbine        | 5/30/2018  | Woodbine Disconnect Switches 814A, 813B, 882   |  | Maritime Link                       |
| 101S-T82     | 101S-B72                                    | 5/31/2018  | 101S-Woodbine        | 6/1/2018   | Woodbine Disconnect Switches 782, 703B, 704A, 713B                                     |  | Maritime Link                       |
| L-6513       | L-6613                                      | 6/1/2018   | 1N-Onslow            | 6/16/2018  | Cut-over of New Line 6613 - Requires and outage to L-6513                              | NB Tie Imports and Exports 300MW, SPS 2 units available,   | Outside Group                       |
| L-7022       | 88S-713, 88S-712, 88S-711, 88S-714, 88S-715 | 6/1/2018   | 101S-Woodbine        | 9/20/2018  | replacement of the Westinghouse GIS equipment at 88S Lingan                            |  | Transmission Engineering (Lakeside) |
| 101S-T81     | 101S-B71                                    | 6/4/2018   | 101S-Woodbine        | 6/4/2018   | 711, 712, 713, 714, 715, GT1/G1, GT2/G2, L-7022  |  | Maritime Link                       |
| L-6040       | 113H-P6040                                  | 6/4/2018   | 91H-Tufts Cove       | 6/5/2018   | Woodbine Disconnect Switches 101S-711A   |  | System Maintenance                  |
| L-6511       | 93N-P6511                                   | 6/4/2018   | 50N-Trenton          | 6/5/2018   | C Inspection 113H-P6040  | Onslow Import: 650MW to Normal depending on Generation in the area, SPS arming levels reduced    | System Maintenance                  |
| L-6552       | 93N-P6552                                   | 6/4/2018   | 4C-Antigonish (Loch. | 6/5/2018   | C Inspection 93N-P6511   | Reducing SPS Arming Levels Limiting Onslow Import based on the sum of the total generation       | System Maintenance                  |
| L-6001       | L-6001 (1N A protection)                    | 6/4/2018   | 1N-Onslow            | 7/18/2018  | C Inspection 93N-P6552   |  | Transmission Engineering (Lakeside) |
| 101S-T81     | 101S-B81                                    | 6/5/2018   | 101S-Woodbine        | 6/5/2018   | New Spider Lake Substation Protection  |  | Maritime Link                       |
| 301NS Pole 1 | 101S-816A & 814B                            | 6/6/2018   | 301NS-Woodbine DC    | 6/6/2018   | Woodbine Disconnect switches 816B, 811A  |  | Maritime Link                       |
| L-6040       | 113H-601                                    | 6/6/2018   | 91H-Tufts Cove       | 6/8/2018   | Woodbine Disconnect Switches 816A, 814B  |  | System Maintenance                  |
| 301NS Pole 2 | 101S-811B & 812A                            | 6/7/2018   | 301NS-Woodbine_DC    | 6/7/2018   | C Inspection 113H-601  |  | Maritime Link                       |
| L-6042       | 113H-P6042                                  | 6/11/2018  | 91H-Tufts Cove       | 6/12/2018  | Woodbine Disconnect Switches   |  | System Maintenance                  |
| L-6548       | 2C-P6548                                    | 6/11/2018  | 2C-Port Hastings     | 6/12/2018  | C Inspection 113H-P6042  |  | System Maintenance                  |
| L-6042       | 113H-642                                    | 6/13/2018  | 91H-Tufts Cove       | 6/15/2018  | C Inspection 2C-P6548  |  | System Maintenance                  |
| L-7019       | 91N-P7019                                   | 6/14/2018  | 67N-Onslow           | 6/14/2018  | C Inspection 113H-642  | Cape Breton Export 620 720, Onslow Import 755 795, SPS limits reduced                            | System Maintenance                  |
| L-7019       | 91N-PB71                                    | 6/14/2018  | 91N-Dalhousie Mtn.   | 6/15/2018  | C Inspection 91N-P7019   | Cape Breton Export 620 720, Onslow Import 755 795, SPS limits reduced                            | System Maintenance                  |
| L-7019       | 91N-P7019                                   | 6/14/2018  | 91N-Dalhousie Mtn.   | 6/15/2018  | C Inspection 91N-PB71  | Cape Breton Export 620 720, Onslow Import 755 795, SPS limits reduced                            | System Maintenance                  |
| L-7011       | 3C-P7011                                    | 6/18/2018  | 3C-Port Hastings     | 6/19/2018  | C Inspection 91N-P7019   | East End X at East Bay - 675 MW, CBX 700 MW, Generation restrictions apply, Lower SPS arming lin | System Maintenance                  |
| L-6043       | 113H-643                                    | 6/18/2018  | 113H-Dartmouth East  | 6/20/2018  | C Inspection 3C-P7011  | Radial feed  | System Maintenance                  |
| PA           | 89S-GT1                                     | 6/21/2018  | 89S-Pt. Aconi        | 6/30/2018  | C Inspection 113H-643  |  | System Maintenance                  |
| PA           | 89S-GT1                                     | 6/26/2018  | 89S-Pt. Aconi        | 7/7/2018   | C Inspection 89S-GT1   |  | System Maintenance                  |
| L-6015       | 43V-P6015                                   | 7/2/2018   | 43V-Cannan Rd.       | 7/2/2018   | 89S-GT1 Paint Transformer  |  | System Maintenance                  |
| L-6015       | 43V-P6015                                   | 7/2/2018   | 43V-Cannan Rd.       | 7/3/2018   | 43V-P6015 "C" maintenance  |  | System Maintenance                  |
| L-5040       | 89N-P5040                                   | 7/2/2018   | 1N-Onslow            | 7/3/2018   | 43V-P6015 "C" maintenance  |  | System Maintenance                  |
| L-7009       | 120H-713                                    | 7/2/2018   | 120H-Brushy Hill     | 7/4/2018   | C Inspection 89N-P5040   | Breaker only, no outage line.  | System Maintenance                  |
| L-6040       | L-6040 (113H protection)                    | 7/25/2018  | 91H-Tufts Cove       | 8/27/2018  | C Inspection 120H-713  |  | Transmission Engineering (Lakeside) |
| L-6040       | L-6040 (91H Protection)                     | 8/15/2018  | 91H-Tufts Cove       | 8/27/2018  | New Spider Lake Switching Station  |  | Transmission Engineering (Lakeside) |
| L-6035       | 104H-635                                    | 9/17/2018  | 1H-Water St.         | 9/19/2018  | C Inspection 104H-635  | Generation Restrictions Apply  | System Maintenance                  |
| L-6040       | L-6040                                      | 9/18/2018  | 91H-Tufts Cove       | 10/2/2018  | Spider Lake Construction   |  | Transmission Engineering (Lakeside) |
| L-6035       | 104H-P6035                                  | 9/20/2018  | 1H-Water St.         | 9/20/2018  | C Inspection 104H-P6035  | Generation Restrictions Apply.   | System Maintenance                  |
| L-6035       | 104H-CT635                                  | 9/20/2018  | 1H-Water St.         | 9/21/2018  | C Inspection 104H-CT635  | Generation Restrictions Apply  | System Maintenance                  |
| L-6035       | 104H-P6035                                  | 9/20/2018  | 1H-Water St.         | 9/21/2018  | C Inspection 104H-P6035  | Generation Restrictions Apply  | System Maintenance                  |
| L-6533       | 88S-B71, 88S-711, 88S-715, 88S-710, 88S-T71 | 9/20/2018  | 2S-Victoria Junction | 9/30/2018  | replacement of the Westinghouse GIS equipment at 88S Lingan                            | 88S-T71 out of service Limit flow through 88ST72 to 170MW Operate local units in synchronous cor | Transmission Engineering (Lakeside) |
| L-6040       | L-6040/L-6044 Split line                    | 9/25/2018  | 91H-Tufts Cove       | 10/2/2018  | 711, 715, 710, B71, T71, L-6533  |  | Transmission Engineering (Lakeside) |
| L-6511       | 4C-P6511                                    | 10/1/2018  | 50N-Trenton          | 10/1/2018  | C Inspection 91H-Tufts Cove  | Onslow Import: 650MW to Normal depending on Generation in the area, SPS arming levels reduced    | System Maintenance                  |
| L-6511       | 4C-P6511                                    | 10/1/2018  | 50N-Trenton          | 10/2/2018  | C Inspection 4C-P6511  | Onslow Import: 650MW to Normal depending on Generation in the area, SPS arming levels reduced    | System Maintenance                  |
| L-7015       | L-7015                                      | 10/2/2018  | 101S-Woodbine        | 10/3/2018  | Woodbine Breakers 101S-713A, 712B, 753   |  | Maritime Link                       |
| L-6001       | L-6001                                      | 10/2/2018  | 1N-Onslow            | 10/9/2018  | Spider Lake Construction   |  | Transmission Engineering (Lakeside) |
| L-6515       | 4C-621 (1 of 2 Breakers on this line)       | 10/3/2018  | 2C-Port Hastings     | 10/5/2018  | C Inspection 4C-621  | Line will remain in service fed by 4C-622  | System Maintenance                  |
| L-7014       | 88S-720 88S-723                             | 10/8/2018  | 88S - Lingan         | 11/12/2018 | Lingan upgrade   | Generation restrictions apply, SPS levels adjusted,  | Transmission Engineering (Lakeside) |