

Line No.	Line / ID	Start Date	From Station	End Date	Short Description / Purpose of Request	System Restrictions	Project Owner
L-6021	9W-516	7/30/2018	30W-Souriquois	8/2/2018	Inspection		System Maintenance
L-6538	L6538 Outage	8/1/2018	5S-Glen Tosh	8/3/2018	Tower painting	Generation restriction apply, Reduce SPS arming levels	Transmission Group (Ragged Lake)
L-6613	74N-613	7/23/2018	1N-Onslow	8/10/2018	Breaker Replacement	NB Tie Imports and Exports 300MW, SPS 2 units available,	System Maintenance
L-7002	L7002 Outage	7/30/2018	67N-Onslow	8/10/2018	Equipment Replacements	Onslow South 670/ 850	Transmission Group (Ragged Lake)
L-6043	113H-643	8/7/2018	113H-Dartmouth East	8/14/2018	Inspection	Radial feed	System Maintenance
L-8004	L-8004	8/15/2018	79N-Hopewell	8/18/2018	Line Upgrades	Hastings From 600MW /625*, L7011+L7012 500 /600, Mainland at Hastings 590 /680, Generation r	Outside Group
L-8002	L8002	3/19/2018	67N-Onslow	8/25/2018	replacement of line protection.		System Maintenance
L-6549	L-6549	8/27/2018	5S-Glen Tosh	8/29/2018	5S-P6549 & 85S-P6549 Testing		System Maintenance
L-6021	L6021 Outage	7/24/2018	30W-Souriquois	8/30/2018	Equipment Replacements		Transmission Group (Ragged Lake)
L-6515	L6515 Outage	8/6/2018	2C-Port Hastings	8/31/2018	Equipment Replacements	Onslow Import 800 to 1000 depending on local generation, Generation Restrictions apply, SPS arming	Transmission Group (Ragged Lake)
L-6001	L-6001 (1N A protection)	8/20/2018	1N-Onslow	9/10/2018	New Spider Lake Substation Protection		Transmission Engineering (Lakeside)
L-7014	101S-703A, 702B, 756	9/11/2018	88S - Lingan	9/11/2018	Disconnect switch upgrade	Generation restrictions apply, SPS levels adjusted,	Outside Group
L-7015	101S- 713A, 712B, 753	9/12/2018	101S-Woodbine	9/12/2018	Disconnect switch upgrade		Outside Group
L-7019	91N-PB71	9/13/2018	91N-Dalhousie Mtn.	9/13/2018	C Inspection 91N-PB71	Cape Breton Export 620 720, Onslow Import 755 795, SPS limits reduced	System Maintenance
L-7019	91N-P7019	9/13/2018	67N-Onslow	9/13/2018	C Inspection 91N-P7019	Cape Breton Export 620 720, Onslow Import 755 795, SPS limits reduced	System Maintenance
PA	89S-GT1	9/10/2018	89S-Pt. Aconi	9/14/2018	C Inspection 89S-GT1		System Maintenance
L-6033	L6033 Outage (2H - 1H)	9/17/2018	103H-Lakeside	9/20/2018	re-conductor and installation of new monopole structure	Generation Restrictions Apply	Transmission Group (Ragged Lake)
L-7021	88S-G1 Node, L-7021 Node at 88S	6/6/2018	101S-Woodbine	9/20/2018	Remove control wiring from breakers and switches		Transmission Engineering (Lakeside)
PA	89S-GT1	9/17/2018	89S-Pt. Aconi	9/21/2018	89S-GT1 Paint Transformer		System Maintenance
L-6035	104H-635	9/16/2018	1H-Water St.	9/21/2018	C Maintenance	Generation Restrictions Apply. Hold Off Restrictions: Line needs to be isolated, restriction can be	System Maintenance
L-6533	88S-B71, 88S-711, 88S-715, 88S-710, 88S-T71	9/20/2018	2S-Victoria Junction	9/30/2018	replacement of the GIS equipment	88S-T71 out of service Limit flow through 88ST72 to 170MW Operate local units in synchronous cor	Transmission Engineering (Lakeside)
L-6511	4C-P6511	10/1/2018	50N-Trenton	10/1/2018	C Inspection 4C-P6511	Onslow Import: 650MW to Normal depending on Generation in the area, SPS arming levels reduced	System Maintenance
L-6511	4C-P6511	10/1/2018	50N-Trenton	10/2/2018	C Inspection 4C-P6511	Onslow Import: 650MW to Normal depending on Generation in the area, SPS arming levels reduced	System Maintenance
L-6040	L-6040 (113H protection)	9/10/2018	91H-Tufts Cove	10/13/2018	New Spider Lake Switching Station		Transmission Engineering (Lakeside)
L-6040	L-6040 (91H Protection)	10/15/2018	91H-Tufts Cove	11/16/2018	New Spider Lake Switching Station		Transmission Engineering (Lakeside)
L-6040	L-6040	11/19/2018	91H-Tufts Cove	11/26/2018	Spider Lake Construction		Transmission Engineering (Lakeside)
L-6040	L-6040/L-6044 Split line	11/12/2018	91H-Tufts Cove	11/26/2018	New Spider Lake Switching Station		Transmission Engineering (Lakeside)
L-7014	L-7014	11/1/2018	88S - Lingan	11/29/2018	Upgrades 88S-720, 723	Generation restrictions apply, SPS levels adjusted,	Transmission Engineering (Lakeside)
L-6001	L-6001	11/26/2018	1N-Onslow	12/3/2018	Spider Lake Construction		Transmission Engineering (Lakeside)

All System Restrictions posted here are the restrictions for that particular element out of service only.

Studies will take place prior to outages to re-define restrictions based on additional elements out of service at that time, and generation patterns.