

Line No.	Line / ID	Start Date	From Station	End Date	Short Description / Purpose of Request	System Restrictions
L-8004	79N-PB81	9/7/2019	79N-Hopewell	9/7/2019	C Inspection 79N-PB81 (B)	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply
L-8004	79N-P8004	9/7/2019	79N-Hopewell	9/7/2019	C Inspection 79N-P8004	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply
L-8004	79N-CT810	9/7/2019	79N-Hopewell	9/7/2019	C Inspection 79N-CT810	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply
L-8004	79N-810	9/7/2019	79N-Hopewell	9/9/2019	C Inspection 79N-810	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply
L-8004	79N-B81	9/7/2019	79N-Hopewell	9/9/2019	NPCC Testing 79N-B81	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply
L-8004	L-8004	3/5/2019	79N-Hopewell	3/7/2019	Canso Crossing tying in the new line	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply
L-8004	L-8004	3/1/2019	79N-Hopewell	3/1/2019	AC fault test	Hastings From 600MW /725, L7011+L7012 500 /600, Mainland at Hastings 570 /680, Generation restrictions apply
L-8003	79N-P8003	7/6/2019	67N-Onslow	7/6/2019	C Inspection 79N-P8003	CBX 600 to 700, Generation restrictions apply, Reduce SPS arming levels
L-8003	79N-CT803	7/6/2019	67N-Onslow	7/6/2019	C Inspection 79N-CT803	CBX 600 to 700, Generation restrictions apply, Reduce SPS arming levels
L-8003	79N-803	7/6/2019	67N-Onslow	7/8/2019	C Inspection 79N-803	CBX 600 to 700, Generation restrictions apply, Reduce SPS arming levels
L-8003	67N-L8003	7/6/2019	67N-Onslow	7/8/2019	NPCC Testing 67N-L8003	CBX 600 to 700, Generation restrictions apply, Reduce SPS arming levels
L-8003	79N-L8003	7/6/2019	67N-Onslow	7/8/2019	NPCC Testing 79N-L8003	CBX 600 to 700, Generation restrictions apply, Reduce SPS arming levels
L-8002	67N-L8002	5/13/2019	67N-Onslow	5/15/2019	NPCC Testing 67N-L8002	Onslow South 700 /875 Flow into Metro 520/525, Onslow Import 1050/1125
L-8002	L-8002	5/13/2019	67N-Onslow	5/14/2019	NPCC Testing 103H-T81	Onslow South 700 /875 Flow into Metro 520/525, Onslow Import 1050/1125
L-8001	67N-L8001	5/1/2019	67N-Onslow	5/3/2019	NPCC Testing 103H- 345 BBU	Onslow South 700 /875 Flow into Metro 520/525, Onslow Import 1050/1125
L-7018	67N-L7018	5/1/2019	67N-Onslow	5/3/2019	NPCC Testing 67N-L7018	Onslow 740/900, Increased MDRR correction by 50 Mvar
L-7015	101S-P7015	9/7/2019	101S-Woodbine	9/7/2019	C Inspection 101S-P7015	
L-7015	101S-L7015	9/7/2019	101S-Woodbine	9/9/2019	NPCC Testing 101S-L7015	
L-7015	89S-L7015	9/7/2019	101S-Woodbine	9/9/2019	NPCC Testing 89S-L7015	
L-7014	101S-P7014	5/1/2019	88S - Ligan	5/1/2019	C Inspection 101S-P7014	Generation restrictions apply, SPS levels adjusted,
L-7012	3C-L7012	5/1/2019	3C-Port Hastings	5/3/2019	NPCC Testing 3C-L7012	End X at East Bay incl PA1 - 735/850 MW, Onslow Import 975/1150. Generation restrictions apply, lower SPS arming limits.
L-7012	88S-L7012	5/1/2019	3C-Port Hastings	5/3/2019	NPCC Testing 88S-L7012	End X at East Bay incl PA1 - 735/850 MW, Onslow Import 975/1150. Generation restrictions apply, lower SPS arming limits.
L-7005	67N-L7005	5/1/2019	67N-Onslow	5/3/2019	NPCC Testing 67N-L7005	Cape Breton Export 850/1000, Onslow Import 1050/1150, SPS arming levels reduced. Mainland at Hastings 340/420
L-7005	3C-L7005	5/1/2019	67N-Onslow	5/3/2019	NPCC Testing 3C-L7005	Cape Breton Export 850/1000, Onslow Import 1050/1150, SPS arming levels reduced. Mainland at Hastings 340/420
L-7005	L7005 Outage	7/15/2019	67N-Onslow	8/9/2019	L7005 Outage	Cape Breton Export 850/1000, Onslow Import 1050/1150, SPS arming levels reduced. Mainland at Hastings 340/420
L-6613	1N-B62	7/1/2019	1N-Onslow	7/3/2019	NPCC Testing 1N-B62	NB Tie Imports and Exports 300MW, SPS available
L-6549	L6549 Outage	9/2/2019	5S-Glen Tosh	10/11/2019	L6549 Outage	
L-6548	L-6548	4/8/2019	2C-Port Hastings	4/30/2019	Port Hastings - 2C Bulk Power System Upgrades project	
L-6543	L-6543	3/18/2019	2C-Port Hastings	4/5/2019	Port Hastings - 2C Bulk Power System Upgrades project	
L-6539	L6539 Outage	6/3/2019	2S-Victoria Junction	7/5/2019	L6539 Outage	Generation restriction apply, Reduce SPS arming levels
L-6537	L-6537	7/23/2019	2C-Port Hastings	8/13/2019	Port Hastings - 2C Bulk Power System Upgrades project	
L-6537	2C-B61	9/19/2019	2C-Port Hastings	10/2/2019	Port Hastings - 2C Bulk Power System Upgrades project	85S Generation restrictions
L-6536	74N-P6536	4/1/2019	74N-Springhill	4/1/2019	C Inspection 74N-P6536	
L-6516	L6516	7/1/2019	2C-Port Hastings	7/5/2019	L6516 outage for structure and insulator replacements. Permit holder TBD. WO TB.D.	
L-6516	L-6516	8/14/2019	2C-Port Hastings	9/4/2019	SP: Required	CBX - 830MW, Onslow Import Normal, Generation restrictions apply
L-6516	L-6516	8/14/2019	2C-Port Hastings	9/4/2019	Port Hastings - 2C Bulk Power System Upgrades project	CBX - 830MW, Onslow Import Normal, Generation restrictions apply
L-6516	2C-B62	9/5/2019	2C-Port Hastings	9/18/2019	Port Hastings - 2C Bulk Power System Upgrades project	CBX - 830MW, Onslow Import Normal, Generation restrictions apply
L-6515	4C-P6515	8/1/2019	2C-Port Hastings	8/1/2019	C Inspection 4C-P6515	Onslow Import 800 to 1000 depending on local generation, Generation Restrictions apply, SPS arming levels reduced
L-6515	2C-640	8/1/2019	2C-Port Hastings	8/3/2019	C Inspection 2C-640	Onslow Import 800 to 1000 depending on local generation, Generation Restrictions apply, SPS arming levels reduced
L-6515	L-6515	7/7/2019	2C-Port Hastings	7/22/2019	Port Hastings 2C Bulk Power System Upgrades	Onslow Import 800 to 1000 depending on local generation, Generation Restrictions apply, SPS arming levels reduced
L-6508	79N-P6508	3/1/2019	50N-Trenton	3/1/2019	C Inspection 79N-P6508	
L-6508	79N-CT601	3/1/2019	50N-Trenton	3/1/2019	C Inspection 79N-CT601	
L-6508	79N-601	3/1/2019	50N-Trenton	3/3/2019	C Inspection 79N-601	
L-6507	79N-P6507	3/1/2019	50N-Trenton	3/1/2019	C Inspection 79N-P6507	
L-6507	79N-CT606	3/1/2019	50N-Trenton	3/1/2019	C Inspection 79N-CT606	
L-6507	79N-606	3/1/2019	50N-Trenton	3/3/2019	C Inspection 79N-606	
L-6503	50N-PB62	7/1/2019	1N-Onslow	7/1/2019	C Inspection 50N-PB62	Onslow Import: 820 MW, Generation Restrictions apply, Lower SPS arming levels. Generation Restrictions
L-6503	1N-P6503	7/1/2019	1N-Onslow	7/1/2019	C Inspection 1N-P6503	Onslow Import: 820 MW, Generation Restrictions apply, Lower SPS arming levels. Generation Restrictions
L-6503	51N-654	7/1/2019	1N-Onslow	7/3/2019	C Inspection 51N-654	Onslow Import: 820 MW, Generation Restrictions apply, Lower SPS arming levels. Generation Restrictions
L-6040	L-6040	4/1/2019	91H-Tufts Cove	4/22/2019	Spider Lake Transmission	

L-6024	9W-P6024	5/1/2019	50W-Milton	5/1/2019	C Inspection 9W-P6024 C Inspection 104H-614	10W must be available for Sync
L-6014	104H-614	5/1/2019	91H-Tufts Cove	5/5/2019		91H Export Corridor Restriction
L-6001	L6001	3/1/2019	1N-Onslow	3/31/2019	Spider Lake Transmission	
L-6001	82V	3/4/2019	1N-Onslow	3/22/2019	C-Maintenance C Inspection 98V-T51 C Inspection 98V-411	
L-5581	L-5581	6/17/2019	77V-Conway	6/28/2019	C Inspection 98V-412	
L-5573	155-504	3/10/2019	25-Victoria Junction	3/13/2019	Replace 155-504	
L-5527	57C-P5527	7/8/2019	57C-Salmon River Lak	7/8/2019	C Inspection 57C-P5527	
L-5527	57C-P5527	7/8/2019	57C-Salmon River Lak	7/8/2019	C Inspection 57C-P5527 (Y)	
L-5527	57C-527	7/8/2019	57C-Salmon River Lak	7/10/2019	C Inspection 57C-527	
L-5527	L5527	7/8/2019	57C-Salmon River Lak	7/17/2019	L5527 Outage - coordinated with 19C wind farm.	
L-5040	1N-540	3/1/2019	1N-Onslow	3/3/2019	C Inspection 1N-540	
L-5027	9W-515	5/1/2019	9W - Tusket Hydro	5/3/2019	C Inspection 9W-515	
67N-T82	67N-T82	7/1/2019	67N-Onslow	7/5/2019	C Inspection 67N-T82	ONI 750 (Group 5 SPS Cannot be Armed) Nothing on the TIE. (8002,8003,6513 must be in service)
101S-T81	101S-PT881	3/1/2019	101S-Woodbine	3/1/2019	C Inspection 101S-PT881	
101S-T81	101S-PB71	3/1/2019	101S-Woodbine	3/1/2019	C Inspection 101S-PB71	
101S-T81	101S-T81	3/1/2019	101S-Woodbine	3/3/2019	NPCC Testing 101S-T81	
301NS Pole 1	301NS Pole 1	8/18/2019	101S-Woodbine	8/21/2019	Pole 1 outage for annual scheduled maintenance	
301NS Pole 2	301NS Pole 2	8/21/2019	101S-Woodbine	8/24/2019	Annual Maintenance on Pole 2	