

Line No.	Line / ID	Start Date	From Station	End Date	Short Description / Purpose of Request	System Restrictions	Project Owner
					Constructing of a new transmission line, L6613, between 1N Onslow and 74N Springhill Substations passing through 81N Debert.		
L-6513	L-6513 (1N-81N)	21/01/2018	1N-Onslow	27/01/2018		NB Tie Imports and Exports 300MW, SPS 2 units available,	Outside Group
L-5027	25W switch upgrades L5027	29/01/2018	9W - Tusket Hydro	02/02/2018	Switch upgrades on L5027 at 25W		System Maintenance
VJ1	83S-G1	29/01/2018	83S-Victoria Junctio	02/02/2018	Repairs to 83S-GT1	25MW	System Maintenance
L-7014	L-7014	05/02/2018	88S - Lingan	02/03/2018	Lingan upgrade	Generation restrictions apply, SPS levels adjusted,	Transmission Engineering (Lakeside)
67N-T81	67N-B81	12/03/2018	67N-Onslow	13/03/2018	NPCC Testing 67N-B81		System Maintenance
67N-T82	67N-B82	14/03/2018	67N-Onslow	15/03/2018	NPCC Testing 67N-B82	ONI 750 (Group 5 SPS Cannot be Armed) Nothing on the TIE. (8002,8003,6513 must be in service)	System Maintenance
L-7005	L-7005	15/03/2018	67N-Onslow	18/03/2018	7005 - PART OF THE SWAP AT THE CAUSEWAY	Cape Breton Export 620 /720, Onslow Import 755 /795, SPS arming levels reduced. Mainland at Hast	Outside Group
L-6511	93N-P6511	02/04/2018	50N-Trenton	03/04/2018	C Inspection 93N-P6511	Onslow Import: 650MW to Normal depending on Generation in the area, SPS arming levels reduced	System Maintenance
1C-684A	1C-684A	02/04/2018		06/04/2018	1C-684A Switch Replacement	Generation Restrictions Apply	System Maintenance
1C-688B	1C-688B	02/04/2018		06/04/2018	1C-688B Switch Replacement	Generation Restrictions Apply	System Maintenance
L-6511	50N-614	04/04/2018	50N-Trenton	06/04/2018	C Inspection 50N-614	Onslow Import: 650MW to Normal depending on Generation in the area, SPS arming levels reduced	System Maintenance
L-6001	L-6001 (1N A protection)	16/04/2018	1N-Onslow	07/05/2018	New Spider Lake Substation Protection		Transmission Engineering (Lakeside)
120H-T72	120H-T72	01/05/2018	120H-BRUSHY HILL	01/05/2018	NPCC Testing 120H-T72	FLOW INTO METRO REDUCED TO 500MW	System Maintenance
L-6613	L-6613 Rebuild	01/05/2018	1N-Onslow	16/05/2018	L-6513 Rebuild - Moved to 2018	NB Tie Imports and Exports 300MW, SPS 2 units available,	Maritime Link
L-6533	88S-B71	01/05/2018	2S-Victoria Junction	05/06/2018	replacement of the Westinghouse GIS equipment at 88S Lingan	88S-T71 out of service Limit flow through 88ST72 to 170MW Operate VJ units in synchronous condens	Transmission Engineering (Lakeside)
L-6012	17V-P6011	07/05/2018	17V-St. Croix	08/05/2018	C Inspection PT 17V-P6011		System Maintenance
L-6013	43V-P6013	14/05/2018	43V-Canaan Rd.	15/05/2018	C Inspection 43V-P6013		System Maintenance
L-6021	9W-516	14/05/2018	30W-Souriquois	16/05/2018	C Inspection 9W-516		System Maintenance
L-6040	L-6040 (113H protection)	14/05/2018	91H-Tufts Cove	15/06/2018	New Spider Lake Switching Station		Transmission Engineering (Lakeside)
L-6004	43V-P6004	21/05/2018	90H-Sackville	22/05/2018	C Inspection 43V-P6004		System Maintenance
L-7014	88S-L7014	21/05/2018	88S - Lingan	23/05/2018	88S-L7014 NPCC Testing	Generation restrictions apply, SPS levels adjusted,	System Maintenance
L-7011	88S-713, 88S-712, 88S-711, 88S-714, 88S-715	21/05/2018	3C-Port Hastings	28/09/2018	replacement of the Westinghouse GIS equipment at 88S Lingan	East End X at East Bay - 675 MW, CBX 700 MW, Generation restrictions apply, Lower SPS arming limits	Transmission Engineering (Lakeside)
L-6013	43V-613	28/05/2018	43V-Canaan Rd.	30/05/2018	C Inspection 43V-613		System Maintenance
L-6040	113H-P6040	04/06/2018	91H-Tufts Cove	05/06/2018	C Inspection 113H-P6040		System Maintenance
L-6552	93N-P6552	04/06/2018	4C-Antigonish (Loch.	05/06/2018	C Inspection 93N-P6552	Reducing SPS Arming Levels Limiting Onslow Import based on the sum of the total Trenton GS gross pr	System Maintenance
L-6040	L-6040 (91H Protection)	04/06/2018	91H-Tufts Cove	06/07/2018	New Spider Lake Switching Station		Transmission Engineering (Lakeside)
L-7011	88S-B72	05/06/2018	3C-Port Hastings	30/09/2018	replacement of the Westinghouse GIS equipment at 88S Lingan	East End X at East Bay - 675 MW, CBX 700 MW, Generation restrictions apply, Lower SPS arming limits	Transmission Engineering (Lakeside)
L-6040	113H-601	06/06/2018	91H-Tufts Cove	08/06/2018	C Inspection 113H-601		System Maintenance
L-6042	113H-P6042	11/06/2018	91H-Tufts Cove	12/06/2018	C Inspection 113H-P6042		System Maintenance
L-6548	2C-P6548	11/06/2018	2C-Port Hastings	12/06/2018	C Inspection 2C-P6548		System Maintenance
L-6042	113H-642	13/06/2018	91H-Tufts Cove	15/06/2018	C Inspection 113H-642		System Maintenance
L-7019	91N-P7019	14/06/2018	67N-Onslow	14/06/2018	C Inspection 91N-P7019	Cape Breton Export 620 720, Onslow Import 755 795, SPS limits reduced	System Maintenance
L-7019	91N-PB71	14/06/2018	91N-Dalhousie Mtn.	15/06/2018	C Inspection 91N-PB71	Cape Breton Export 620 720, Onslow Import 755 795, SPS limits reduced	System Maintenance
L-7019	91N-P7019	14/06/2018	91N-Dalhousie Mtn.	15/06/2018	C Inspection 91N-P7019	Cape Breton Export 620 720, Onslow Import 755 795, SPS limits reduced	System Maintenance
L-7011	3C-P7011	18/06/2018	3C-Port Hastings	19/06/2018	C Inspection 3C-P7011	East End X at East Bay - 675 MW, CBX 700 MW, Generation restrictions apply, Lower SPS arming limits	System Maintenance
L-6043	113H-643	18/06/2018	113H-Dartmouth East	20/06/2018	C Inspection 113H-643	Radial feed	System Maintenance
PA	89S-GT1	21/06/2018	89S-Pt. Aconi	30/06/2018	C Inspection 89S-GT1		System Maintenance
PA	89S-GT1	26/06/2018	89S-Pt. Aconi	07/07/2018	89S-GT1 Paint Transformer		System Maintenance
L-6040	L-6040	01/07/2018	91H-Tufts Cove	28/07/2018	Spider Lake Construction		Transmission Engineering (Lakeside)
L-6015	43V-P6015	02/07/2018	43V-Cannan Rd.	02/07/2018	43V-P6015 "C" maintenance		System Maintenance
L-6015	43V-P6015	02/07/2018	43V-Cannan Rd.	03/07/2018	43V-P6015 "C" maintenance		System Maintenance
L-5040	89N-P5040	02/07/2018	1N-Onslow	03/07/2018	C Inspection 89N-P5040		System Maintenance
L-7009	120H-713	02/07/2018	120H-Brushy Hill	04/07/2018	C Inspection 120H-713	Breaker only, no outage line.	System Maintenance
L-6001	L-6001	02/07/2018	1N-Onslow	28/07/2018	Spider Lake Construction		Transmission Engineering (Lakeside)
L-6040	L-6040/L-6044 Split line	09/07/2018	91H-Tufts Cove	23/07/2018	New Spider Lake Switching Station		Transmission Engineering (Lakeside)
L-6035	104H-635	17/09/2018	1H-Water St.	19/09/2018	C Inspection 104H-635	Generation Restrictions Apply	System Maintenance
L-6035	104H-P6035	20/09/2018	1H-Water St.	20/09/2018	C Inspection 104H-P6035	Generation Restrictions Apply.	System Maintenance
L-6035	104H-CT635	20/09/2018	1H-Water St.	21/09/2018	C Inspection 104H-CT635	Generation Restrictions Apply	System Maintenance
L-6035	104H-P6035	20/09/2018	1H-Water St.	21/09/2018	C Inspection 104H-P6035	Generation Restrictions Apply	System Maintenance
L-6511	4C-P6511	01/10/2018	50N-Trenton	01/10/2018	C Inspection 4C-P6511	Onslow Import: 650MW to Normal depending on Generation in the area, SPS arming levels reduced	System Maintenance
L-6511	4C-P6511	01/10/2018	50N-Trenton	02/10/2018	C Inspection 4C-P6511	Onslow Import: 650MW to Normal depending on Generation in the area, SPS arming levels reduced	System Maintenance
L-6515	4C-621 (1 of 2 Breakers on this line)	03/10/2018	2C-Port Hastings	05/10/2018	C Inspection 4C-621	Line will remain in service fed by 4C-622	System Maintenance